

INVOICE

INVOICE NUMBER 958-0344561		INVOICE DATE 03/19/2017	
BILL TO Attn: RICH MARTIN CITY OF DELRAY BEACH 100 NW 1ST AVE DELRAY BEACH FL 33444		CLIENT CODE CIT452001 BUSINESS LINE / LOSS TYPE HE - Heavy Truck and Tractor	
FOR INQUIRIES: PDA Miami/Fort Lauderdale, FL #958 pdamiami@pdaorg.net (305) 821-6500		SUBMIT PAYMENT TO: Property Damage Appraisers, Inc. TIN: 75-1160563 PO Box 471909 Fort Worth, TX 76147 <i>Please reference the invoice number and enclose a copy of the invoice on all payments.</i>	
INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
CITY OF DEL RAY BEACH		03/13/2017	958-703-0237
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
UNIT 201668			
T&E: 5.40 hours @ \$95.00 Mileage: (30.00 miles - 0 included) @ \$1.10 \$ 513.00 \$ 33.00			
Thank you for your business!			
Terms: Professional fees due upon receipt. Interest accrues at 1% per month. Please reference the invoice number and enclose a copy of the invoice on all payments.		TOTAL CHARGES:	546.00
		INVOICE TOTAL:	\$ 546.00

Date: 3/17/2017 11:14 AM
 Estimate ID: 9587030237
 Estimate Version: 0
 Committed
 Profile ID: * PDA FL H.E

Property Damage Appraisers (PDA Miami, Fort Lauderdale)

P.O. Box 222785, Hollywood, FL 33022-2785
 (305) 821-6500
 Fax: (305) 821-9600
 Email: pdamiami@pdaorg.net

Not An Authorization For repair
 Read disclaimers following appraisal calculations.

Please send all supplements via email to PDAMiami@pdaorg.net or fax to 305-821-9600.

Damage Assessed By: Orlando Fontela
 Classification: Field

Appraised For: RICH MARTIN

Condition Code: Good
 Contact Date: 3/14/2017
 Deductible: 0.00
 File Number: 9587030237
 Claim Number: UNIT 201668

Type of Loss: Collision

Insured: City of Delray Beach
 Owner: City of Delray Beach
 Address: 100 NW 1ST AVE, Delray Beach, FL 33444
 Telephone: Work Phone: (561) 243-7000

Mitchell Service: 910665

Description: 2016 Freightliner M2
 Type/Component: Truck
 VIN: 1FVACWDUXGHHN3050
 Mileage: 1
 OEM/ALT: O
 Color: RED

Vehicle Production Date: 9/15
 Drive Train:
 License: XF2351 FL
 Search Code: 958

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
1	931117	BDY	REMOVE/REPLACE	Left Front Tire	New	454.98	* 0.4*
2				Michelin XZE 245/70R19.5			
3	931118	BDY	REMOVE/REPLACE	Right Front Tire	New	454.98	* 0.4*
4				Michelin XZE 245/70R19.5			
5	001547	BDY	OVERHAUL	Frt Bumper Assy			1.7
6	900500	BDY *	ADD'L LABOR OP	Cut Holes Cntr, Pads	Existing		2.0*
7	900500	BDY *	REMOVE/REPLACE	Wheelhouse Panel, Alum L	New	268.50	* 4.0*
8	900500	BDY *	REMOVE/REPLACE	Seal, Fender Rear L	New	22.18	* 0.2*
9	900500	BDY *	ADD'L LABOR OP	Cut Hole, Bumper End L	Existing		2.0*
10	900500	MCH*	REPAIR	Harness, Speaker L	Existing		2.0*
11	000007	BDY	REMOVE/INSTALL	R Frt Bumper End	Existing		0.0*#
12	000008	BDY	REMOVE/REPLACE	L Frt Bumper End	N.A.	580.47	* 0.0*#
13	000009	BDY	REMOVE/REPLACE	Frt Ctr Bumper	N.A.	895.72	* 0.0*
14	000011	BDY	REMOVE/REPLACE	R Frt Bumper Mounting Bracket	N.A.	84.07	* 0.2 #
15	000012	BDY	REMOVE/REPLACE	L Frt Bumper Mounting Bracket	N.A.	50.94	* 0.2 #
16	000016	BDY	REMOVE/REPLACE	Grille	N.A.	420.06	* 0.0*
17	900500	BDY *	REMOVE/INSTALL	Emergency Sig Lamps, Grille	Existing		2.5*
18	000017	BDY	CHECK/ADJUST	Headlamps			0.5
19	000021	BDY	REMOVE/REPLACE	L Frt Combination Lamp Assembly	N.A.	199.05	* 0.0*
20	001979	BDY	REMOVE/REPLACE	L Frt Combination Lamp Bezel	N.A.	81.65	*
21	000029	BDY	REMOVE/REPLACE	L Frt Side Repeater Lamp Assembly	N.A.	34.04	* 0.3
22	000047	REF	REFINISH	Hood Outside			C 5.8

ESTIMATE RECALL NUMBER: 03/17/2017 11:14:44 9587030237

Mitchell Data Version: OEM: MAR_17_V0315

Copyright (C) 1994 - 2017 Mitchell International
 All Rights Reserved

Software Version: 7.1.215

Page 1 of 5

23	000048	REF	REFINISH	Add For Inside				C 2.3
24	002478	REF	REFINISH	Skirt Panel				1.5
25	000053	BDY	REMOVE/REPLACE	Hood Panel	N.A.		2,914.36	* 6.0
26	900500	BDY *	ADD'L LABOR OP	Add for Aux Emrgency Signal & Horns	Existing			3.0*
27				Include Drill Holes				
28	002438	BDY	REMOVE/INSTALL	Hood Release Cable Handle	Existing			0.2* r
29	000064	BDY	REMOVE/REPLACE	L Hood Grille	N.A.		192.14	* 0.3
30	000067	BDY	REMOVE/REPLACE	L Hood Latch	N.A.		39.70	* 0.2
31	000069	BDY	REMOVE/REPLACE	L Hood Latch Bracket	N.A.		6.84	* 0.2
32	000139	REF	REFINISH	L Fender Outside				C 2.3
33	000141	REF	REFINISH	L Add For Inside				C 0.9
34	000145	BDY	REMOVE/REPLACE	L Lwr Fender Panel	N.A.		386.49	* 0.7
35	000167	MCH	REMOVE/REPLACE	L ABS Retainer	-M	N.A.	8.24	* 0.6 #
36	000169	MCH	REMOVE/REPLACE	L ABS Frt Sensor	-M	N.A.	65.16	* 0.6 #
37	001248	REF	REFINISH	L Frame Rail				C 3.0
38	001249	REF	REFINISH	Crossmember				C 1.0
39	000181	FRM	REPAIR	L Frame Rail	-F	Existing		2.5*#
40	000182	FRM	REPAIR	Frame Front Crossmember	-F	Existing		4.0*#
41	000186	BDY	REPAIR	L Frame Tow Hook		Existing		0.3*
42		REF	REFINISH/REPAIR	L Frame Tow Hook				0.3*
43	001264	BDY	REMOVE/REPLACE	Battery Cover	N.A.		155.60	* 0.1
44	900500	BDY *	REMOVE/REPLACE	Roller Tracks, Batt	New		164.50	* 1.0*
45	001265	BDY	REMOVE/REPLACE	Battery Box	N.A.		309.31	* 1.0 #
46				Lower Plate				
47	001870	MCH	REMOVE/REPLACE	L Fuel System Tank	-M	N.A.	937.71	* 1.1
48	000243	BDY	REMOVE/REPLACE	L Fuel System Tank Strap		N.A.	90.22	* 0.2*
49	900500	BDY *	REMOVE/REPLACE	Tank Insulator		New	43.28	* 0.3*
50	900500	BDY *	REMOVE/REPLACE	Isolator 2@10.73		New	21.46	* 0.0*
51	900500	MCH*	REMOVE/REPLACE	Tank Assy, DEF		New	752.44	* 2.0*
52	900500	MCH*	REMOVE/REPLACE	DEF Fluid		New	49.95	* 0.0*
53	900500	MCH*	REMOVE/REPLACE	Tank, Cap		New	42.86	* 0.0*
54	000245	BDY	REMOVE/REPLACE	L Fuel System Bracket 2@159.55		N.A.	319.10	* 0.6 #
55	001814	BDY	REMOVE/REPLACE	Alloy Wheel		N.A.	520.94	* 0.0*#
56	000301	MCH	OVERHAUL	Frt Axle Assy	-M			12.0
57	000312	MCH	REMOVE/REPLACE	R Otr Frt Susp Wheel Bearing	-M	N.A.	51.88	* 1.5*#
58	000313	MCH	REMOVE/REPLACE	L Otr Frt Susp Wheel Bearing	-M	N.A.	51.88	* 1.0*#
59	000317	MCH	REMOVE/REPLACE	L Frt Susp Brake Drum	-M	N.A.	579.66	* 1.5 #
60	000320	MCH	REMOVE/REPLACE	R Inr Frt Susp Wheel Bearing	-M	N.A.	36.95	* 1.0*#
61	000321	MCH	REMOVE/REPLACE	L Inr Frt Susp Wheel Bearing	-M	N.A.	36.95	* 1.0*#
62	000325	MCH	REMOVE/REPLACE	L Frt Susp Brake Assy	-M	N.A.	192.59	* 3.0*#
63	900500	MCH*	REMOVE/REPLACE	Caliper, Brake L		New	175.16	* 0.5*
64	900500	MCH*	REMOVE/REPLACE	Hose, Hyd		New	35.67	* 0.2*
65	000342	MCH	REMOVE/REPLACE	L Frt Susp Spindle	-M	N.A.	643.03	* 4.0*
66	000350	MCH	REMOVE/REPLACE	Frt Susp Axle Beam	-M	N.A.	895.65	* 0.0*
67	000393	MCH	REMOVE/REPLACE	R Frt Susp Leaf Spring	-M	N.A.	531.23	* 1.6 #
68	000394	MCH	REMOVE/REPLACE	L Frt Susp Leaf Spring	-M	N.A.	531.23	* 1.6 #
69	000397	MCH	REMOVE/REPLACE	R Frt Susp U-Bolt	-M 2@22.03	N.A.	44.06	* 0.4*#
70	000398	MCH	REMOVE/REPLACE	L Frt Susp U-Bolt	-M 2@22.03	N.A.	44.06	* 0.4*#
71	000405	MCH	REMOVE/REPLACE	R Frt Susp Shock Absorber	-M	N.A.	83.38	* 0.5 #
72	000406	MCH	REMOVE/REPLACE	L Frt Susp Shock Absorber	-M	N.A.	83.38	* 0.5 #
73	000428	MCH	REMOVE/REPLACE	Bleed Power Assisted Steering	-M			0.3
74	900500	MCH*	REMOVE/REPLACE	Steering Link		New	184.50	* 0.5*
75	000429	MCH	REMOVE/REPLACE	Steering Gear	-M	N.A.	1,088.87	* 3.2
76	000430	MCH	REMOVE/REPLACE	Steering Pitman Arm	-M	N.A.	171.19	* 1.0 #
77	000431	MCH	REMOVE/REPLACE	Steering Drag Link	-M	N.A.	235.62	* 1.0*#
78	002357	MCH	REMOVE/REPLACE	Steering Fluid Reservoir	-M	N.A.	67.62	* 0.8
79	900500	MCH*	REMOVE/REPLACE	King Pin, L		New	412.09	* 1.0*
80	900500	MCH*	REMOVE/REPLACE	Fuel Filter Head, Assy		New	120.84	* 0.4*
81	000597	BDY	REMOVE/REPLACE	Battery 2@137.50		N.A.	275.00	* 0.6*
82	002494	GLS	REMOVE/INSTALL	Windshield				4.3 #
83	002498	BDY	REMOVE/REPLACE	W/Shield Adhesive		N.A.	34.95	* 0.0*
84	900500	BDY *	REMOVE/REPLACE	Lamp, Shield		New	21.88	* 0.2*
85	900500	BDY *	REMOVE/REPLACE	Panel, Cowl L		New	85.62	* 0.5*
86	900500	BDY *	REMOVE/REPLACE	Seal, Ins Therm		New	81.47	* 0.3*
87	001771	MCH	REMOVE/REPLACE	Instrument Panel	-M			7.0*

ESTIMATE RECALL NUMBER: 03/17/2017 11:14:44 9587030237

Mitchell Data Version: OEM: MAR_17_V0315

Copyright (C) 1994 - 2017 Mitchell International
All Rights Reserved

Page 2 of 5

Software Version: 7.1.215

Date: 3/17/2017 11:14 AM
Estimate ID: 9587030237
Estimate Version: 0
Committed
Profile ID: * PDA FL H.E

88	001297	REF	REFINISH	Upr Cowl Panel				C 1.0
89	000625	BDY	REPAIR	Cab Support	Existing			4.0*
90	000626	BDY	REMOVE/REPLACE	Cab Cowl Top Panel (HSS)	N.A.	523.59	*	3.0*
91	001300	REF	REFINISH	L Cowl Panel				C 0.8
92	001308	REF	REFINISH	L Cab Door Opening Frame				C 1.5
93	001310	REF	REFINISH	L Add For Inside				C 0.6
94	000628	BDY	REMOVE/REPLACE	L Cab Cowl Side Panel (HSS)	N.A.	186.00	*	2.0*
95	000634	BDY	REMOVE/REPLACE	L Cab Door Opening Frame	N.A.	1,002.85	*	8.9
96	000636	BDY	REMOVE/REPLACE	L Cab Pillar Cover	N.A.	73.37	*	0.7
97	001320	REF	REFINISH	L Side Panel Assy				C 2.6
98	000648	BDY	REPAIR	L Cab Side Panel	Existing			12.5*
99	900500	BDY *	REMOVE/INSTALL	Roll Door Assy, L	Existing			3.0*
100	900500	BDY *	REMOVE/INSTALL	Grab Handle, L	Existing			0.3*
101	000737	BDY	REPAIR	Cab Floor Pan	Existing			8.0*#
102	900500	BDY *	REMOVE/REPLACE	Undercoating	New	250.00	*	3.0*
103	000751	BDY	REPAIR	L Cab Support	Existing			4.0*#
104	000848	BDY	REMOVE/INSTALL	L Cab Treadplate	Existing			0.2* r
105	000850	BDY	REMOVE/INSTALL	L Lwr Cab Trim Panel	Existing			0.2* r
106	000852	BDY	REMOVE/INSTALL	Cab Headliner	Existing			1.5* r
107	900500	BDY *	REMOVE/INSTALL	Interior to Access Rpr	Existing			5.0*
108	001393	REF	REFINISH	L Frt Door Outside				C 3.1
109	001395	REF	REFINISH	L Frt Add For Jambs & Interior				C 1.0
110	002383	BDY	REMOVE/REPLACE	L Frt Door Shell	N.A.	1,111.58	*	5.0
111	001012	BDY	REMOVE/REPLACE	L Frt Door Auxiliary Mirror	N.A.	72.43	*	0.1
112	936004		ADD'L COST	Shipping		495.00	*	
113	900500	MCH*	REMOVE/REPLACE	Steering, Oil	New	28.95	*	0.0*
114	900500	MCH*	REMOVE/REPLACE	Oil, Hyd	New	34.90	*	0.0*
115	936007		ADD'L COST	Shop Materials		595.00	*	
116				Fasteners, Abrasive, Welding Supplies				
117	900500	FRM *	ALIGN	Hinge Pillar/Floor Pull, L	Existing			3.0*
118	900500	MCH*	ALIGN	Front & Rear Axle Alignment	Sublet	312.50	*	0.0*
119	936012		ADD'L COST	Hazardous Waste Disposal		14.90	*	
120	936019		ADD'L COST	Caulking Materials		49.95	*	
121	900500	BDY *	REMOVE/REPLACE	Hub Cover, L	New	113.61	*	0.2*
122	900500	BDY *	REMOVE/REPLACE	Lug Covers	New	5.52	*	0.0*
123	900500	BDY *	REMOVE/REPLACE	Chrome Flange	New	15.59	*	0.3*
124	900500	BDY *	ALIGN	Square Cab, CA	Existing			8.0*
125	900500	BDY *	REPAIR	Corner Post, L Frt	Existing			3.0*
126		REF	REFINISH/REPAIR	Corner Post, L Frt				2.0*
127	900500	BDY *	REMOVE/REPLACE	Corner Plate Protc, Alum L	New	212.50	*	3.0*
128	900500	BDY *	REMOVE/REPLACE	Rubrail, L	New	297.50	*	3.0*
129	900500	BDY *	REMOVE/REPLACE	Molding Wheel, L	New	128.40	*	1.5*
130	933006	FRM	ADD'L OPR	Frame/Rack Set Up				3.0*
131	933030	FRM	ADD'L OPR	Pull For Sway				4.0*
132	900500	MCH*	REPAIR	Bleed/Purge HYD	Existing			1.0*
133	933017	REF	ADD'L OPR	Finish Sand And Buff		0.00	*	14.0*
134				Module Panel, L				
135	933018	REF	ADD'L OPR	Mask For Overspray		10.00	*	0.5*
136	900500	MCH*	REMOVE/REPLACE	Control Module	New	627.04	*	2.8*
137	900500	MCH*	REMOVE/REPLACE	Wiring Harness	New	335.09	*	5.5*
138	900500	BDY *	REMOVE/REPLACE	Vinyl Graphics/Reflective 3M	Sublet	945.00	*	0.0*
139				Southeast Truck Specialist Sublet				
140	900500	BDY *	ALIGN	Remove Vinyl Logos/Decals	Existing			6.0*
141				Remove Residual Adhesive				
142	900500	MCH*	REMOVE/REPLACE	Plug Harness, Converter	New	52.50	*	1.2*
143	900500	BDY *	REMOVE/REPLACE	Horn, Hood	New	238.84	*	0.5*
144	900500	BDY *	REMOVE/REPLACE	Tank Cover, Alum DP L	New	3,574.78	*	4.0*
145	900500	BDY *	REMOVE/REPLACE	Tank Cover, Rear DEF Batt L	New	3,179.23	*	3.0*
146	900500	BDY *	REMOVE/REPLACE	Siren Speaker, L	New	866.69	*	0.5*
147	900500	BDY *	REMOVE/REPLACE	Louvered Panel, Alum L 2@269.40	New	538.80	*	4.0*
148	900500	BDY *	REMOVE/REPLACE	Signal, L	New	197.40	*	0.6*
149	900500	BDY *	REMOVE/REPLACE	SS Panel, L	New	148.00	*	2.0*
150	900500	MCH*	REMOVE/REPLACE	Tie Rod, L	New	320.64	*	0.3*
151	900500	MCH*	REMOVE/REPLACE	Tie Rod, R	New	320.64	*	0.3*
152	AUTO		ADD'L COST	Paint/Materials		1,039.50	*	

ESTIMATE RECALL NUMBER: 03/17/2017 11:14:44 9587030237

Mitchell Data Version: OEM: MAR_17_V0315

Copyright (C) 1994 - 2017 Mitchell International
All Rights Reserved

Page 3 of 5

Software Version: 7.1.215

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Remarks

Horton Ambulance/Rescue Body Module
Model 623-1
Serial No C041617185

Estimate Totals

I.	Labor Subtotals	<u>Units</u>	<u>Rate</u>	<u>Add'l Labor Amount</u>	<u>Sublet Amount</u>	<u>Totals</u>	II.	Part Replacement Summary	<u>Amount</u>
	Body	131.1	95.00	0.00	0.00	12,454.50 T		Taxable Parts	32,764.79
	Refinish	44.2	95.00	10.00	0.00	4,209.00 T			
	Glass	4.3	95.00	0.00	0.00	408.50 T		Total Replacement Parts Amount	32,764.79
	Frame	16.5	95.00	0.00	0.00	1,567.50 T			
	Mechanical	63.3	95.00	0.00	312.50	6,326.00 T			
	Taxable Labor				24,965.50				
	Labor Summary	259.4		24,965.50					
III.	Additional Costs					<u>Amount</u>	IV.	Adjustments	<u>Amount</u>
	Taxable Costs					2,144.40		Insurance Deductible	0.00
	Non-Taxable Costs					49.95		Customer Responsibility	0.00
	Total Additional Costs					2,194.35			
	Paint Material Method: Rates								
	Init Rate = 35.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
	I.	Total Labor:						24,965.50	
	II.	Total Replacement Parts:						32,764.79	
	III.	Total Additional Costs:						2,194.35	
		Gross Total:						59,924.64	
	IV.	Total Adjustments:						0.00	
		Net Total:						59,924.64	

Point(s) of Impact

11 Left Front Corner (P), 9 Left Side (S)

Insurance Co: CITY OF DELRAY BEACH
Address: 100 NW 1ST AVE
DELRAY BEACH, FL 33444
Work Phone: (561) 243-7151

Inspection Site: Southeast Truck Specialist
Address: 2407 Hammondville Road
Pompano Beach, FL 33444
(954) 970-3651

Inspection Date: 3/14/2017

ESTIMATE RECALL NUMBER: 03/17/2017 11:14:44 9587030237

Mitchell Data Version: OEM: MAR_17_V0315

Copyright (C) 1994 - 2017 Mitchell International
All Rights Reserved

Software Version: 7.1.215

Body Shop: Southeast Truck Specialist
Address: 2407 Hamondville Road
Pompano Beach, FL 33069
Telephone: (954) 970-3651
Fax Phone: (954) 970-4201

*****Notice*****

This is not an authorization for repair. All costs of repairs are the sole responsibility of the vehicle owner, who must authorize all repairs. Failure to deliver a copy of this appraisal to the repair shop by the vehicle owner may result in out of pocket expense to the vehicle owner. Providing a copy of this appraisal is not an acceptance of coverage or liability and all issues of coverage or liability are to be determined by the insurance carrier.

*****Notice*****

Deductibles may or may not be addressed or included in this appraisal. If applicable, the repairer should collect the deductible from the vehicle owner prior to the release of the repaired vehicle.

*****Supplement Procedure Notice*****

It is the repairer's responsibility to send notification of the supplement via fax or email to PDA (305-821-9600) or (pdamiami@pdaorg.net), including a statement whether the repairs have been halted on the vehicle. PDA will respond to your request within 24 hours. Please allow 48 hours to complete supplement processing from the date of request to ensure timely release of the vehicle

*****Notice*****

This appraisal is subject to the complete review and approval by the assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.

"Failure to use the insurance proceeds in accordance with the security agreement, if any, could be a violation of § 812.014, Florida Statutes. If you have any questions, contact your lending institution." "Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application containing any false, incomplete, or misleading information is guilty of a felony of the third degree." "This paragraph shall not apply to reinsurance contracts, reinsurance agreements, or reinsurance claims transactions.

"

Review Results: Failures (0), Warnings (2)

Owner: City of Delray Beach, Claim #UNIT 201668

Vehicle: 2016 Freightliner, M2

Profile: 1 PDA Standard Version: 27

Page 1 of 1

Estimate lines

Line	Severity	Description	Actual	Guideline	Override	Notes
		Estimate lines Passed				

Profile (rates, taxes, amounts)

Line	Severity	Description	Actual	Guideline	Override	Notes
		Profile items Passed				

Administrative Information

Line	Severity	Description	Actual	Guideline	Override	Notes
	Warning	Vehicle Options missing			Yes	Yes
ON CONDITION REPORT						
	Warning	Loss Date missing			Yes	Yes
NOT PROVIDED						

Form F107A Rev. 6/15

PDA Offices Independently Owned and Operated



TRUCK APPRAISER'S REPORT

					PDA Office: 958 MIAMI			
Appraised For: City of Delray Beach			Claim Number: Unit 201668			Assignment Number: 958-703-0237		
Owner: City of Delray Beach			Date of Loss: Unk			☒ Insured ☐ Claimant		
Make: Freightliner			Model: M2 Horton T1 Rescue Module			Year: 2016	VIN: 1FVACWDUXGHHN3050	
Odometer: UNK - Elec disabled		Hubometer (Yes/No/NA): NO	Hub Hours:	Engine Hours: NO		Recent Engine Overhaul: UNK		
Engine	Make: Cummins	Model: ISB	☐ Gas ☒ Diesel ☐ Alternative Fuel			Horsepower: 325		
Transmission	Make: Eaton		Model: RTO 14710			Speeds: 6		
Front Axle	Capacity: 15660	Steering Gear: TRW	Dual Steering Gear (Y/N): No	☒ Power ☐ Manual				
Rear Axle	Make: Meritor		Model: RS 19-224		☒ Single ☐ Tandem ☐ Tri Axle ☐ Tag			
Rear Suspension	Make: Airliner		Type: Air		Capacity: 23000			
Brakes	☐ Hydraulic ☒ Air ☐ Vacuum Assist							
Fifth Wheel	Make: N/A	☐ Fixed ☐ Slider ☐ Manual ☐ Air						
Fuel Tanks	☐ Aluminum ☒ Steel ☐ Polished ☐ Painted ☐ Step ☐ Paddled ☐ Saddle					Number: 1	Capacity: 60	
Cab	☐ COE ☒ Conventional ☐ Sleeper ☐ Integrated						Sleeper Size and Type: N/A	
Equipment	☐ Wet Kit ☐ Owner/Operator PTS ☒ A/C ☐ Heated Mirror							
Exterior	☐ Special Paint ☐ Custom Pin Stripes ☐ Murals Number of Colors: 1							
Frame	☒ Steel ☐ Aluminum ☐ Heat Treated ☐ Reinforced ☐ Standard Length ☐ Extended Length							
Front Wheels	☒ Aluminum ☐ Steel		☒ Polished ☐ Chrome		☐ Painted ☐ Disc		☒ Bud ☐ Dayton	Size: 19.5
Rear Wheels	☒ Aluminum ☐ Steel		☒ Polished ☐ Chrome		☐ Painted ☐ Disc		☒ Bud ☐ Dayton	Size: 19.5
Front Tires	Size: 245/70	Make: MICHELIN	RF 15/32 LF 15/32		☒ Radial ☐ Recaps			
Rear Tires	Size: 295/80/22.5	LRFO 15/32	RRFO 14/32		☒ Radials			
		LRFI 15/32	RRFI 14/32					
	Make: MICHELIN	LRRO N/A/32	RRRO N/A/32		☐ Recaps			
Loss Type	☒ Collision ☐ Fire ☐ Theft ☐ Flood ☐ Other:							
Recommendation	☒ Repairable ☐ Total Loss			Towing: NO	Storage/Day:	Recovery Fee:		
Repair Facility: Southeast Truck Specialist	Phone Number: 954-970-3651	Repair Facility Contact: Joe Guerrero	Agreed Cost To Repair: Yes	Repair Days: 15	Est. ACV: 167,400	Est. Salvage:		
Recommendations:	I met with Joe at Southeast Truck Specialist and he pointed out the truck and left front collision damage. Major left front corner collision damage with additional secondary damage to left side cab and module. Front axle is currently removed but was set back on impact. Left front wheel and lower door opening contact damage. Extensive left side door opening and cab cowl panel damage. Left side aluminum diamond plate fuel tank, def, and battery cover removed from truck, but shop provided photos of damaged parts. Battery acid stains on brite alum module covers. Several aux components and signal lamps broken (please reference estimate for list). A copy of the repair appraisal has been forwarded to Joe with Southeast Truck Specialist. Parts Quoted by Loubachrodt Freightliner & Horton Parts Dept.							
General Condition:	Overall truck and body is in good condition							

Prior Damage:	Minor wear and tear	
Betterment:	None	
Alternative Parts:	None	
Temporary Repairs:	None	
Appraiser:	Orlando Fontela	Date: 3/17/2017



Document Name: 1 VIN.jpg

Remarks:



Document Name: 10 RIGHT FRONT.jpg

Remarks:



Document Name: 11 RIGHT FRONT.jpg

Remarks:



Document Name: 12 RIGHT REAR.jpg

Remarks:



Document Name: 13 RIGHT REAR.jpg

Remarks:



Document Name: 14 LEFT REAR.jpg

Remarks:



Document Name: 15 LEFT REAR.jpg

Remarks:



Document Name: 16 BODY MANF SERIAL LABEL.jpg

Remarks:



Document Name: 17 POI LEFT FRONT CORNER AND SIDE.jpg

Remarks:




Document Name: 18 HOOD PANEL DAMAGE.jpg

Remarks:



Document Name: 19 LEFT SIDE HOOD PANEL DAMAGE.jpg

Remarks:



Document Name: 2 VIN.jpg

Remarks:



Document Name: 20 LEFT SIDE SIGNAL LAMP AND HOOD LATCH DAMAGE.jpg

Remarks:



Document Name: 21 LEFT SIDE HOOD GRILLE AND HORN DAMAGE.jpg

Remarks:



Document Name: 22 SIGNAL LAMP DAMAGE.jpg

Remarks:



Document Name: 23 LEFT SIDE HEADLAMP BROKEN OFF.jpg

Remarks:



Document Name: 24 GRILLE EMERGENCY LAMPS.jpg

Remarks:



Document Name: 25 RIGHT SIDE HEADLAMP AND HORN.jpg

Remarks:



Document Name: 26 LEFT SIDE CAB DAMAGE.jpg

Remarks:



Document Name: 27 LEFT SIDE CONVEX MIRROR CRACKED.jpg

Remarks:



Document Name: 28 LEFT SIDE MIRROR BRACKET.jpg

Remarks:



Document Name: 29 LEFT SIDE BUMPER END AND CENTER BUMPER DAMAGE.jpg

Remarks:

3/14/2017

SNA, LLC	GAWR/PNBE KGS	GAWR/PNBE LBS	TIRES	RIMS	KPA COLD	PSI COLD	"S"
FRONT AXLE:	4,481	9,880	245/70R19.5(H)	19.5X6.75	827	120	S
1ST INT AXLE:							
2ND INT AXLE:							
3RD INT AXLE:							
4TH INT AXLE:							
5TH INT AXLE:							
6TH INT AXLE:							
REAR AXLE:	6,804	15,000	245/70R19.5(H)	19.5X6.75	827	120	D

Document Name: 3 MANF LABEL.jpg

Remarks:



Document Name: 30 STEERING RESERVOIR CRACKED.jpg

Remarks:



Document Name: 31 FUEL FILTER HEAD CRACKED.jpg

Remarks:



Document Name: 32 STEERING RESERVOIR CRACKED.jpg

Remarks:



Document Name: 33 SPLASHGUARD FENDER CRACKED.jpg

Remarks:



Document Name: 34 CONTROL MODULE DAMAGE.jpg

Remarks:



Document Name: 35 CONTROL MUDULE RECP DAMAGE.jpg

Remarks:



Document Name: 36 CONTROL MODULE HARNESS DAMAGE CRUSHED.jpg

Remarks:



Document Name: 37 WINDSHIELD COWL PANEL AND WS REINF DAMAGE.jpg

Remarks:



Document Name: 38 LEFT SIDE FRAME RAIL.jpg

Remarks:



Document Name: 38 STEERING GEAR.jpg

Remarks:



Document Name: 39 COWL SEAL.jpg

Remarks:



Document Name: 4 NO ODO.jpg

Remarks:



Document Name: 40 LEFT SIDE COWL SIDE PANEL.jpg

Remarks:



Document Name: 41 LOWER DOOR FRAME OPENING AND FLOOR DAMAGE.jpg

Remarks:



Document Name: 42 LEFT SIDE REAR CAB PANEL SS COVER DAMAGE.jpg

Remarks:



Document Name: 43 LEFT SIDE REAR CAB PANEL DAMAGE.jpg

Remarks:



Document Name: 44 LEFT SIDE REAR CAB PANEL POST DAMAGE BY ROLL UP DOOR.jpg

Remarks:



Document Name: 45 DEF TANK DAMAGE.jpg

Remarks:



Document Name: 46 LEFT SIDE REAR CAB PANEL DAMAGE.jpg

Remarks:



Document Name: 47 DEF TANK CAP MISSING.jpg

Remarks:



Document Name: 48 BATTERY TRAY AND ROLLERS.jpg

Remarks:



Document Name: 49 LEFT SIDE MODULE CORNER POST CONTACT DAMAGE.jpg

Remarks:



Document Name: 5 INTERIOR DOOR.jpg

Remarks:



Document Name: 50 LEFT SIDE MODULE.jpg

Remarks:



Document Name: 51 LEFT SIDE VENTED ALUM PANEL ACID STAINED.jpg

Remarks:



Document Name: 52 ALUMINUM PANELS STAINED WITH BATTERY ACID.jpg

Remarks:




Document Name: 53 RUBRAIL L STAINED WITH BATTERY ACID.jpg

Remarks:



Document Name: 54 BATTERY ACID STAINS.jpg

Remarks:



Document Name: 55 WHEELHOUSE ALUM PANEL BATTERY ACID STAINS.jpg

Remarks:



Document Name: 56 LEFT SIDE WHEEL AND TIRE DAMAGE.jpg

Remarks:



Document Name: 57 LEFT SIDE WHEEL DAMAGE.jpg

Remarks:



Document Name: 58 RIGHT SIDE TIRE SLICED.jpg

Remarks:



Document Name: 59 RIGHT SIDE TIRE.jpg

Remarks:



Document Name: 6 INSTRUMENT PANEL.jpg

Remarks:



Document Name: 60 STEER LINK.jpg

Remarks:



Document Name: 61 HUB COVER DAMAGE.jpg

Remarks:



Document Name: 62 FRONT AXLE REMOVED.jpg

Remarks:



Document Name: 63 FRONT AXLE.jpg

Remarks:



Document Name: 64 CALIPER SHEARED OFF.jpg

Remarks:




Document Name: 65 PLUG CONV DAMAGE.jpg

Remarks:



Document Name: 7 LICENSE.jpg

Remarks:



Document Name: 8 INTERIOR MODULE.jpg

Remarks:



Document Name: 8 LEFT FRONT.jpg

Remarks:



Document Name: 9 FRONT.jpg

Remarks: