Estimate ID: 1308 Estimate Version: 0 **Preliminary** 

Profile ID:

\* Joseph Hanin 55610518 Quote ID:

#### FLORIDA FRAUD WARNING:

\*\*\* Any person who knowingly and with intent to injure, defraud, or Deceive any insurer files a statement of claim containing any false, Incomplete, or misleading information is guilty of a Felony of the Third degree.

HIDDEN DAMAGE -TEAR DOWN WOULD BE NECESSART-.

VEH. IS A TOTAL LOSS

## Joseph Hanin Appraisal

P.O. Box 221893, Hollywood, FL 33022-1893 (954) 925-0535 Email: haninappraisals@aol.com

Damage Assessed By: JOSEPH HANIN Appraised For: RICH MARTIN

(561) 243-7585

Classification: None

Condition Code: Good Type of Loss: Comprehensive (Spec)

Arrival Date: 9/27/2019 Contact Date: 9/27/2019 Deductible: UNKNOWN Claim Number: 1308

Insured: CITY OF DELRAY BEACH

Claimant: UNIT #1308

Mitchell Service: 911354

**Description: 2013 Ford Taurus Police** Vehicle Production Date: 8/12

Body Style: 4D Sed

Drive Train: 3.5L Inj 6 Cyl 6A AWD VIN: 1FAHP2M81DG148686 License: XC6710 FL

Mileage: 72,329

OEM/ALT: A Search Code: B66514 Color: WHITE

Line	Entry	Labor		Line Item	Part Type/	Dollar	Labor
Item	Number	Type	Operation	Description	Part Number	Amount	Units
				Air Bag System			
1	100777	MCH	REMOVE/REPLACE	Air Bag Module-Driver Front -M	DG1Z 78043B13 AA	377.09	0.5
2	101754	MCH	REMOVE/REPLACE	Air Bag Restraint Control Module -M	EG1Z 14B321 B	530.77	0.5 #
3		BDY	REMOVE/INSTALL	Ctr Console			8.0
4	100788	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System -M			INC
5	100789	MCH	REMOVE/REPLACE	Air Bag System Diagnosis -M			1.1 #
6	100791	MCH	REMOVE/REPLACE	L Air Bag Side Curtain Module -M	BG1Z 54042D95 B	655.95	INC #
7		BDY	REMOVE/INSTALL	Roof Headliner			INC
8	100801	MCH	REMOVE/REPLACE	L Rear Air Bag Side Impact Sensor -M	BK2Z 14B004 A	86.50	INC #
				Wheel			
9	100818	BDY	REMOVE/REPLACE	Wheel	** QUAL REPL PART	110.00	0.3
10				LEFT REAR			
				Exhaust			

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V

MAPP:SEP\_19\_V Copyright (C) 1994 - 2019 Mitchell International

**Software Version:** 7.1.237 **All Rights Reserved** 

Estimate ID: 1308 Estimate Version: 0

Preliminary Profile ID:

\* Joseph Hanin 55610518 Quote ID:

					Quote ID: 55	610518
11	100924	MCH	REMOVE/REPLACE	Rear Exhaust Muffler -M	DG1Z 5230 D	698.45 1.4
				Rear Door		
12	101272	BDY	REMOVE/INSTALL	L Rear Door Assembly		0.6
13	101275	BDY	REPAIR	L Rear Door Shell	Existing	1.0*
14		REF	REFINISH	L Rear Door Outside		C 2.1
15	101282	BDY	REMOVE/INSTALL	L Rear Upr Door Moulding		0.2
16	101284	BDY	REMOVE/INSTALL	L Rear Door Sash Moulding		0.5 #
17	101286	BDY	REMOVE/INSTALL	L Rear Otr Door Belt Moulding		INC
18	101298	BDY	REMOVE/INSTALL	L Rear Door Trim Panel		0.4
19	100273	BDY	REMOVE/INSTALL	L Rear Otr Door Handle		0.3
20	101356	BDY	REMOVE/REPLACE	L Rear Upr Door Hinge	DG1Z 5426801 A	43.37 0.3 #
21	101330	REF	REFINISH	L Rear Upr Hinge	DG12 3420001 A	C 0.5
22	404250				DC47 E426944 A	
	101358	BDY	REMOVE/REPLACE	L Rear Lwr Door Hinge	DG1Z 5426811 A	
23		REF	REFINISH	L Rear Lwr Hinge		C 0.5
				Special/Manual Entry		A = 1
24	900500	BDY *	REMOVE/INSTALL	INTERIOR	Existing	2.5* r
				<u>Roof</u>		
25	100101	BDY	REMOVE/REPLACE	Roof Panel	AG1Z 5450202 A	773.78 19.5
26		REF	REFINISH	Roof Panel Outside		C 2.6
27		MCH	REMOVE/REPLACE	Add To R&I/R&R Side Curtain Air Bags -M		4.4
28	100135	BDY	REMOVE/REPLACE	Roof Rear Reinforcement	AG1Z 5451269 B	35.23 1.0
29	100136	BDY	REMOVE/REPLACE	Rear Roof Header Panel	AG1Z 5442220 A	52.11 1.5
30	102280	BDY	REMOVE/REPLACE	R Roof Moulding	EG1Z 5451728 D	141.41 INC
31	102281	BDY	REMOVE/REPLACE	L Roof Moulding	EG1Z 5451729 D	141.41 INC
32	102471	BDY	REMOVE/REPLACE	Roof Headliner	DG1Z 5451916 CF	2,053.44 INC
32	10247 1	וטטו	KEWOVE/KEF LACE	Back Window	DG12 3431310 CI	2,033.44
22	404660	CLC	DEMOVE/DEDLACE		CC47 E442006 B	20E 47 INC #
33	101662	GLS	REMOVE/REPLACE	Back Window Glass	CG1Z 5442006 B	385.17 INC #
34	100202	GLS	REMOVE/REPLACE	Back Window Adhesive	N.A.	25.00 *
				Quarter Panel		
35	100032	BDY	REPAIR	R Quarter Outer Panel	Existing	6.0*#
36		REF	REFINISH	R Quarter Panel Outside		C 1.8
37	100033	BDY	REMOVE/REPLACE	L Quarter Outer Panel	AG1Z 5427841 A	1,239.27 14.0 #
38		MCH	REMOVE/REPLACE	L Add To R&I/R&R Side Curtain Air Bags-M		INC #
39		MCH	REMOVE/REPLACE	L Rear Add To R&I/R&R Side Air Bag Senso		0.3
40		REF	REFINISH	L Quarter Panel Outside		C 1.8
41		REF	REFINISH	L Add For Pillar		C 0.5
42		REF	REFINISH	L Quarter Panel Edge		C 0.5
43	100042	BDY	REMOVE/REPLACE	L Quarter Wheelhouse Liner	AG1Z 5428371 A	37.85 INC
44	100046	BDY	REMOVE/REPLACE	L Quarter Rivet	* W712650 S417	3.50
45	100050	BDY	REMOVE/REPLACE	L Inr Quarter Wheelhouse Panel -S	DG1Z 5427791 A	530.05 5.5
46	100030	BDY		L Quarter Side Reinf (HSS)	8A5Z 5428409 A	60.82 1.5
40	100107	וטט	REMOVE/REPLACE	Special/Manual Entry	6A32 3420403 A	00.02 1.3
47	000500	DDV *	DEMONEUNICIALL		Frieding	_
47	900500	BDY *	REMOVE/INSTALL	POLICE EQUIPMENT LIGHTS ON ROOF	Existing	r
				Quarter Panel		
48	100110	BDY	REMOVE/REPLACE	L Quarter Retainer	AG1Z 54466A10 A	9.89
49	100120	BDY	REMOVE/REPLACE	L Upr Quarter Trim Panel	BG1Z 5452019 AB	90.66 INC
50	100123	BDY	REMOVE/REPLACE	Quarter Package Tray Trim Panel	ORDER FROM DEALER	585.97 INC #
51	100168	BDY	REMOVE/REPLACE	L Rear Quarter Speaker	DG1Z 18808 F	112.33 0.2 #
				Luggage Lid		
52	100179	BDY	REPAIR	Luggage Lid Panel	Existing	2.0*
53		REF	REFINISH	Luggage Lid Outside	•	C 2.0
54	100180	BDY	REMOVE/REPLACE	Luggage Lid Latch Assy	DG1Z 5443200 A	133.84 0.3
55	100183	BDY	REMOVE/REPLACE	R Luggage Lid Hinge	DG1Z 5442700 A	50.58 0.4 #
56		REF	REFINISH	R Hinge	20.20.12.00 A	C 0.5
57		BDY	REMOVE/INSTALL	-		0.5
	100184	BDY	REMOVE/REPLACE	Luggage Lid Assy	DG1Z 5442701 A	50.58 0.4 #
58 50	100104			L Luggage Lid Hinge	DG12 3442/01 A	
59	4000==	REF	REFINISH	L Hinge	DO47 F444040 * *	C 0.5
60	100255	BDY	REMOVE/REPLACE	Luggage Lid Moulding	DG1Z 5441018 AA	327.40 INC
61	100054	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Nameplate	XW7Z 5442528 AC	24.86 0.2

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V
MAPP:SEP\_19\_V
Software Version: 7.1.237

Copyright (C) 1994 - 2019 Mitchell International

All Rights Reserved

3.00 \*

5.00 \*

5.00 \*

10.00 \*

579.80 \*

2.0\*

8.0\*

3.0\*

3.8

1.0\*

Estimate ID: 1308 **Estimate Version:** 0

**Preliminary** Profile ID: \* Joseph Hanin 55610518 Quote ID:

					Quote ID: 55	0010518
				Rear Body		
62	101424	BDY	REMOVE/REPLACE	Rear Body Panel	AG1Z 5440320 A	213.29 7.3 #
63		REF	REFINISH	Rear Body Panel		C 1.6
64		REF	REFINISH	Add For Edge & Inside		C 1.0
65	101425	BDY	REMOVE/REPLACE	Rear Body Rear Floor Pan -S	DG1Z 5411215 A	2,559.70 20.0 #
66	101413	BDY	REMOVE/REPLACE	Rear Body Front Bracket	8A8Z 5A204 A	43.88
67	100011	BDY	REMOVE/REPLACE	L Rear Body Floor Pan Reinf (HSS)	DG1Z 9B007 C	1,180.51 1.2 #
68	101441	BDY	REMOVE/REPLACE	Rear Body Rear Floor Reinf (HSS)	DG1Z 9B007 D	1,225.19 INC #
69	101600	BDY	REMOVE/REPLACE	Rear Body Stud	* W715562 S439	3.50
				Rear Lamps		
70	101629	BDY	REMOVE/INSTALL	R Rear Combination Lamp		INC
71	102073	BDY	REMOVE/REPLACE	L Rear Combination Lamp	DG1Z 13405 CC	176.31 INC
72	101717	BDY	REMOVE/REPLACE	L Backup Lamp Assembly	DG1Z 13405 M	166.76 0.5 #
				Rear Bumper		
73	101643	BDY	OVERHAUL	Rear Bumper Cover Assy		0.8
74	101646	BDY	REMOVE/REPLACE	Rear Bumper Cover	** QRP Certified	453.00 INC
75		REF	REFINISH	Rear Bumper Cover		C 2.6
76	101569	BDY	REMOVE/REPLACE	Rear Bumper Extension	** QUAL REPL PART	189.00 INC #
77		BDY	REMOVE/INSTALL	Rear Bumper Cover		INC
78	101576	BDY	REMOVE/REPLACE	Rear Bumper Energy Absorber	** QRP Certified	132.00 INC
79	101577	BDY	REMOVE/INSTALL	Rear Bumper Impact Bar (UHSS)	Existing	INC #r
				Additional Costs & Materials		
80	936001		ADD'L COST	Towing		50.00 *

Additional Operations

Additional Costs & Materials

* - Judgment Item	*	- J	ud	am	ent	Item
-------------------	---	-----	----	----	-----	------

<sup># -</sup> Labor Note Applies

ADD'L COST

ADD'L COST

ADD'L OPR

ADD'L OPR

ADD'L OPR

ADD'L OPR

ADD'L OPR

ADD'L OPR

**ADD'L COST** 

**KEYSTONE-INS QUALITY PRT** 5621 45TH ST. **WEST PALM BEACH** FL 33407 (407) 845-3700 (800) 794-5312

82

83

84

85

86

87

88

89

936012

936014

933006

933031

933036

933005

933018

FRM

FRM

FRM

REF

BDY

REF

KSI - MIAMI. FL 5499 NW 145TH ST. #111 **OPA LOCKA** FL 33054 (305) 888-4466 (800) 566-0800

**Hazardous Waste Disposal** 

**Restore Corrosion Protection** 

Flex Additive

**Pull For Mash** 

**Clear Coat** 

**Sheetmetal Pull** 

Paint/Materials

Frame/Rack Set Up

**Mask For Overspray** 

453.00 74 \*\* FO1100684C 9 \*\* 2190591 110.00 76 \*\* FO1115107C 189.00 78 \*\* 2167583Q 132.00

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V MAPP:SEP\_19\_V

Copyright (C) 1994 - 2019 Mitchell International

**Software Version:** 7.1.237 All Rights Reserved

<sup>\*\*</sup> QRP Certified - Quality Replacement Parts - Certified

<sup>\*\*</sup> QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Estimate ID: 1308
Estimate Version: 0
Preliminary

Profile ID: \* Joseph Hanin Quote ID: 55610518

### **Estimate Totals**

ı.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	91.0	44.00	5.00	0.00	4,009.00 T		Taxable Parts	15,750.28
	Refinish	22.3	44.00	10.00	0.00	991.20 T			
	Frame	13.0	85.00	0.00	0.00	1,105.00 T		Total Replacement Parts Amount	15,750.28
	Mechanical	8.2	95.00	0.00	0.00	779.00 T			
		Taxable L	.abor			6,884.20			
	Labor Summary	134.5				6,884.20			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs	<b>;</b>				587.80		Customer Responsibility	0.00
	Non-Taxable Costs					50.00			
	Total Addition	al Costs				637.80			
	Paint Material Init Rate = 26.0			99.9, Addl Ra	ate = 0.00				
							I.	Total Labor:	6,884.20
							II.	Total Replacement Parts:	15,750.28
							III.	Total Additional Costs:	637.80
								Gross Total:	23,272.28
							IV.	Total Adjustments: Net Total:	0.00 23,272.28 TOTAL LOSS

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. THE AFTERMARKET CRASH PARTS USED IN THE PREPARATION OF THIS ESTIMATE ARE WARRANTED BY THE MANUFACTURER OR DISTRIBUTOR OF SUCH PARTS, RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

# This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
12 Front Center (P)

Insurance Co: CITY OF DELRAY BCH

Inspection Site: CITY OF DELRAY BCH

Inspection Date: 9/27/2019

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V

MAPP:SEP\_19\_V Copyright (C) 1994 - 2019 Mitchell International

Software Version: 7.1.237 All Rights Reserved

Page 4 of 5

Estimate ID: 1308
Estimate Version: 0
Preliminary

Profile ID: \* Joseph Hanin Quote ID: 55610518

This is not a repair Authorization or acceptance of liability.

- \* \* Authorization must be obtained from the owner of the vehicle. Please provide a copy of this appraisal to your repair facility prior to your authorization to repair the vehicle. Failing to present this Appraisal to the repair facility before repairs may result in Additional expense to the vehicle owner.
- \* \* No supplemental repairs are authorized without prior approval from

The insurance appraisal services or the insurance company. Insurance Appraisal services will not be liable for repairs that exceed 75%\*\*\* of the current market value of the owners vehicle due to Unauthorized supplemental repairs performed by the repair facility.

- \* \* Any supplemental charges must be supported by documents such as Receipts, or parts invoices, or other documents as required by the Insurance company.
- \* \* This estimate may include the use of quality repair replacement Parts supplied by other sources than the original manufacturer of your

Vehicles. The manufacturer or distributors of the parts provide Warranties applicable to these replacement parts. The usage of any Sheet metal parts are subject to the CAPA certification.

- \* \* All appraisals are subject to review by the insurance company to Assure accuracy, cost effectiveness, and that accepted industry Standards are met.
- \* \* Any person who knowingly presents a false or fraudulent claim for Payment of a loss is subject to criminal and civil penalties. The Vehicle owner may be responsible for paying betterment on replacement Parts that are subject to ordinary wear pursuant to the terms of their

Insurance policy.

\* \* This is not a final approved estimate, nor an acceptance to pay. The Supervisor will review the estimate and give final approval And/or may request an additional audit or solicit additional Information to make an informed payment decision.

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V

MAPP:SEP\_19\_V Software Version: 7.1.237

Date: 9/29/2019 08:10 AM ate ID: 1308

**Amount** 

15,750.28

23,272.28

23,272.28

0.00

Estimate ID: 13
Estimate Version: 0
Preliminary

II. Part Replacement Summary

**Gross Total:** 

**Total Adjustments:** 

**Net Total:** 

IV.

**Taxable Parts** 

Profile ID: \* Joseph Hanin Quote ID: 55610518

## **Itemized Totals**

	Remove/Replace	74.4	"	3,273.60			New	14,866.28
	Repair	9.0	"	396.00			**Qual Repl Part	884.00
	Remove/Install	5.8	"	255.20			·	
	Overhaul	8.0	"	35.20				
	Additional Operation (\$)	0.0	N/A	5.00				
	Additional Operation	1.0	"	44.00				
	Refinish	22.3	44.00	991.20 ¹T			Total Replacement Parts Amount	15,750.28
	Refinish Only	18.5	44.00	814.00				
	Additional Operation (\$)	0.0	N/A	10.00				
	Additional Operation	3.8	"	167.20				
	Frame	13.0	85.00	1,105.00 T				
	Additional Operation	13.0	"	1,105.00				
	Mechanical	8.2	95.00	779.00 T				
	Remove/Replace	8.2	"	779.00				
	Taxable Labor			6,884.20				
	Labor Summary 134.5			6,884.20				
III.	Additional Costs				Amount	IV/	Adirestments	Amount
III.						IV.	Adjustments	
	Taxable Costs				587.80		Customer Responsibility	0.00
	Non-Taxable Costs				50.00			
	<b>Total Additional Costs</b>				637.80			
	Paint Material Method: Init Rate = 26.00 , Init N		= 99.9, Ad	dl Rate = 0.00				
							Total Labor.	6 004 00
						I. II.	Total Labor: Total Replacement Parts:	6,884.20 15,750.28
						III.	Total Additional Costs:	637.80
						ш.	i otal Additional Costs.	037.00

Units

91.0

Rate

44.00

**Totals** 

4,009.00 <sup>1</sup>T

ESTIMATE RECALL NUMBER: 09/29/2019 08:09:55 1308

Mitchell Data Version: OEM: SEP\_19\_V MAPP:SEP\_19\_V

I. Labor Subtotals

----/D--l---

Body

MAPP:SEP\_19\_V Copyright (C) 1994 - 2019 Mitchell International

Software Version: 7.1.237 All Rights Reserved

<sup>&</sup>lt;sup>1</sup> Total includes Additional Labor (\$) dollar amounts as shown within the group