

FOUNDING PRINCIPALS

Robert J. McNamara, P.E., S.E. Joseph A. Salvia, P.E.

MANAGING PRINCIPALS

Boston

Mark F. Aho, P.E. Neil A. Atkinson John S. Matuszewski, P.E. Adam C. McCarthy, P.E. Benjamin B. Wild, P.E.

Miami

Andrew P. Sullivan, P.E., S.E.

New York

Ryan A. Dow, P.E., S.E. Vladimir E. Seijas, P.E. Bart A. Sullivan, P.E. August 16, 2021

Via E-Mail: jhochman@pebbcap.com

C/O Jared Hochman
VP of Development
Pebb Capital Management
7900 Glades Road, Suite 540
Boca Raton, FL 33434

RE: Unsafe Structures – Block 69 Building Z Delray Beach, Florida Mc/Sal Project No 19446.002

To Whom It May Concern:

McNamara Salvia visited the project site to observe the existing conditions of Building Z and Block 69. The enclosed is a summary of our findings as it specifically pertains to the structure.

The following are a few images of the outside of the structure overall:





It is our understanding that this home consists of two separate structures that were combined with a single-story flat roof connector.

The home to the east is generally in good condition inside and from the exterior. The connector between the two homes is in very poor condition with

ONE BISCAYNE TOWER - SUITE 3795 - 2 SOUTH BISCAYNE BOULEVARD - MIAMI, FL 33131 - T: 305.579.5765 - FL CA #26616 MCSAL.COM



the roof and ceiling collapsed exposing the roof joists. The following are several connector photos:












ONE BISCAYNE TOWER * SUITE 3795 * 2 SOUTH BISCAYNE BOULEVARD * MIAMI, FL 33131 * T: 305.579.5765 * FL CA #26616 MCSAL.COM





The enclosed photos are from the west, two-story home and illustrates holes in the roof directly allowing rain into the interior space both upstairs and downstairs.









ONE BISCAYNE TOWER - SUITE 3795 - 2 SOUTH BISCAYNE BOULEVARD - MIAMI, FL 33131 - T: 305.579.5765 - FL CA #26616 MCSAL.COM





In conclusion, based on the above, we recommend the immediate demolition and removal of the connection between the original two home structures and the removal of the home to the west. Upon demolition and removal, those areas should be reevaluated for structural integrity as partial demo may compromise the structural integrity of the remaining building. Please let us know if you have any further questions.

Very truly yours,

McNamara • Salvia

Andrew P. Sullivan, P.E., S.E.

Principal