

2016-036
Chevy Parts and Service
City of Delray Beach

Part	Roger Dean Chevrolet Inc. Received 11/30/15 @ 1039 AM	AutoNation.com Received 11/30/15 @0950 AM
A/C ACTUATOR, IMPALA	28.85	29.12
LUG NUT	4.31	4.35
BRAKE ROTOR, IMPALA FRONT	86.11	86.90
RELAY	9.24	9.33
BRAKE ROTOR, PPV TAHOE FRONT	73.03	73.70
SENSOR, TIRE PRESSURE	48.22	48.66
EXHAUST HANGER	8.92	9.00
HEADLAMP, IMPALA RH	177.03	178.65
HEADLAMP, IMPALA LH	177.03	178.65
RELAY	7.66	7.73
BRAKE ROTOR, IMPALA REAR	62.13	62.60
BRAKE PADS, IMPALA REAR	61.04	61.60
BRAKE PADS, IMPALA FRONT	82.84	83.60
BRAKE PADS, IMPALA PPV FRONT	80.66	81.80
SENSOR	44.13	44.54
NUT	4.31	4.35
BRAKE ROTOR, IMPALA FRONT	86.11	86.90
BRAKE PADS, PPV TAHOE FRONT	139.52	140.80
BLADE KIT, COOLING FAN	32.49	32.79
TIRE PRESSURE SENSOR	44.13	44.54
BLADE KIT, COOLING FAN	31.90	32.30
MOTOR, COOLING FAN	88.78	89.60
COPPER WASHER	0.43	0.43
TIRE PRESSURE SENSOR	49.03	49.50
HUB, IMPALA FRONT	95.03	95.90
MOTOR, COOLING FAN	84.78	85.56
THERMOSTAT	33.84	34.16
RADIATOR HOSE, LOWER	41.04	41.42
RAIN GUARD	68.67	69.30
TAIL LAMP, IMPALA LH	100.31	101.23
MOUNT, IMPALA ENGINE	73.71	74.38
CONNECTOR, COOLING FAN MOTOR	17.12	17.28
PURGE VALVE	25.12	25.36
INSULATOR, STEERING STABILIZER	6.49	6.55
STRUT, HOOD SUPPORT	18.17	18.34
STRUT, FRONT SUSPENSION	46.42	46.85
HANDLE, TAILGATE	78.36	79.08
HUB ASSEMBLY	156.51	157.95
LOCK CYLINDER, TRUNK	70.25	70.90
HEATER CONTROL	141.61	142.91
% OF MARKUP FROM WHOLESALE COST	Cost + 9%	10.00%
TOTAL	2,485.33	2,508.61