



City Manager's Report

Subject: Street Lights in Rain Berry Woods

Upon visual inspections both at night and during the day time there are insufficient street lights located in Rain Berry Woods to provide adequate security especially given the large number of vehicles located in the area. The present street lights provided are insufficient in number and in illumination and do not meet City standard.