

Photograph 1: Aerial view of site, showing east elevation.



Photograph 2: View of site from Interstate 95 exit ramp, facing northwest.



Photograph 3: East Elevation (Partial)



Photograph 4: South Elevation



Photograph 5: South and West Elevations




Photograph 6: West Elevation



Photograph 7: West Elevation, facing southeast



Photograph 8: North and West Elevations



Photograph 9: East Elevation, facing southwest




Photograph 10: North Elevation



Photograph 11: North side of property, facing south



Photograph 12: Interior



Photograph 13: Interior (Fire training setup)



Photograph 14: Interior of Warehouse, west wall



Photograph 15: Interior of Warehouse, east wall (City storage of holiday decorations)



Photograph 16: Interior of Warehouse, west and north walls



Photograph 17: Interior of Warehouse (Panoramic view of west, north, and east walls)