

Before and After Photos

West
Elevation



Non- Contributing
Addition Removed

East
Elevation



Removed non-contributing addition
and walls for East expansion.



South
Elevation



Removed portion of South
Addition not previously
approved. See Justification
statement.



North
Elevation



Removed non-contributing
carport enclosure not
previously approved. See
Justification statement

Current Photos Prior to Stop order.

Northwest Area Garage Footers format



West Elevation Footers prepped for stone planters designed to restore historical footprint



South addition Footers format




One of five Helical piles cut into existing slab to support weight of new raised slab



East wall footer formatted for east addition and retaining wall footers formatted for East Retaining wall to raise FEMA elevation



Footers formatted for South Retaining Wall to raise FEMA elevation



Progress Photos
(1-12-24 – 3-6-24)

Footers poured, Pilings added, stem walls built.



Foundation prepped with fill for raised slab. Plumbing, HVAC and Electrical Ground Roughs

