
File No. 21-1980 Renovated





## LOCATED AT:

212 Seabreeze Avenue Delray Beach, FL 33483

## CLIENT:

Michael Marco 212 Seabreeze Avenue Delray Beach, FL, 33483

# AS OF:

October 1, 2021

# BY:

David Aucamp, SRA Cert Res RD366

# Residential Appraisal Report

File No. 21-1980 Renovated

ш	The purpose of this apprais Client Name/Intended User		<b>`</b>			ail <b>micheallmar</b>				ic uppruise	di.	
DS			, 			Delray Beach	oowyma			ate FL	Zip 33483	
PURPOSE	Additional Intended User(s)	N/A										
Ъ	Intended Use The intend	ed use of the re	eport is to as	sist the client i	n filing for a buildin	g permit with th	ne City o	f Delra	ay Beach.			
					-							
L	Property Address 212 Sea Owner of Public Record Mi				City	Delray Beach				ate FL ounty Paln	Zip 33483 n Beach	
JEC <sup>-</sup>	Legal Description Lot 21 &			elray Beach Es	planade, PB 18, P	39						
SUB	Assessor's Parcel # 12-43					Year 2020					26,195.00	
• •	Neighborhood Name Delr Property Rights Appraised	X Fee Simple		ehold Othe	Map er (describe)	Reference 43-4	6-16		Ce	ensus Tract	t 0074.10	
					ubject property for the	three years prior to	o the effec	tive dat	te of this appraisa	Ι.		
	Prior Sale/Transfer: Da		oubleat propa	Price		rce(s)	or haa ra	acara	had the subies		historyinformati	on for the
	Analysis of prior sale or tran preceding three year p	-									history informati	on for the
DRΥ												
SALES HISTORY												
ES F												
SAL												
	Offerings, options and contr	racto ac of the offer	ativo data of th	o opproised Th	a aubicat property	is not ourrently	under e	ontroo	t nor hoo it ho	on offere	d for colo in the	post voor
	Offerings, options and contr	Tacts as of the ener	clive date of th	e appraisai <u>m</u>	e subject property	is not currently	under c	ontrac	a, nor has it be	en ollere	a for sale in the	pasi year.
	Neighborhoo	Suburban	s Rural	Property Values	One-Unit Housi	ng Trends Stable	Declinir	20	One-Unit Hou PRICE	ising AGE	Present Lan One-Unit	d Use % 60 %
	Built-Up X Over 75%	25-75%	Under 25%	Demand/Supply		In Balance	Over Su	-	\$(000)	(yrs)	2-4 Unit	5 %
	Growth Rapid	X Stable	Slow	Marketing Time	X Under 3 mths	3-6 mths	Over 6 I		430 Low	0	Multi-Family	25 %
DOD	Neighborhood Boundaries	See Attached	Addendum						34,000 High 3,700 Pred.		Commercial Other Vacant	8 % 2 %
<b>JRH</b> (	Neighborhood Description	See Attached	Addendum						<b>3,700</b> Pieu.	00	Uther Vacani	2 70
HBC												
<b>NEIGHBORHOOD</b>												
	Market Conditions (including	g support for the a	bove conclusio	ons) There are	indications of incr	easing prices o	over the p	oast fe	w years. Casl	n or conv	ventional financi	ng
	prevalent in the subject			-			-		-			
	Dimensions 100.03' x 11	3.19' x 100' x 1	15.16'	Area 114'	19 sf	Shape I	Rectang	ular		View Re	esidential	
	Specific Zoning Classificatio			5	scription Single fami	<u> </u>						
	Zoning Compliance X Is the highest and best use			ing (Grandfathere red (or as propose			(describe) ent use?		Yes No	If No dos	cribe. See Attac	hed
	Addendum	or the subject prop	city us improv		a per plans and speen					1110, 003		
Щ		Other (describe)				)ther (describe)			Off-site Improv		-Type Publi	- Duburtu
SIT	Electricity X Gas X			Water	X				Street Asphal	4	<u> </u>	c Private
	Site Comments Easeme			Sanitary Sev	ver X	$\square$			Alley None	t		
		ents are those of	of public rec	,	ver X se conditions or end	croachments ne	oted at th	he time	Alley None		<u> </u>	
		ents are those of	of public rec	,	0	croachments n	oted at th	he time	Alley None		<u> </u>	
		ents are those o	of public rec	,	0	Croachments no	oted at th	he time	Alley None		<u> </u>	
		ents are those of	of public rec	,	0	Croachments n	oted at th	he time	Alley None		<u> </u>	
	GENERAL DE	ESCRIPTION		FOUNI	DATION	EXTERIOR DES	CRIPTION	N r	Alley None e of inspection materials	INTERIO	R mate	erials
	GENERAL DE			ord. No advers	se conditions or en		CRIPTION s Ste	N r eel Pie	Alley None e of inspection materials			erials
	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att.	ESCRIPTION //Acc. unit	X C	FOUNI FOUNI oncrete Slab	DATION Crawl Space Partial Basement N/A sq. ft.	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface	CRIPTION s Sta Fra Me	N r eel Pie ame & embra	Alley None e of inspection materials ers & Glass	INTERIO Floors Walls Trim/Finis	R mate Wood,Tile Drywall sh Wood	erials
	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos	ESCRIPTION //Acc. unit	Const. Baser	FOUNI FOUNI oncrete Slab	DATION Crawl Space Partial Basement N/A sq. ft. N/A %	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs	CRIPTION s Ste Fra Me spouts Nc	N r eel Pie ame & embra	Alley None e of inspection materials ers & Glass ne	INTERIO Floors Walls Trim/Finis Bath Floo	R mate Wood, Tile	erials
	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att.	ESCRIPTION //Acc. unit	Const. Baser	FOUNI FOUNI oncrete Slab	DATION Crawl Space Partial Basement N/A sq. ft.	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface	CRIPTION s Sta Fra Me spouts Nc Alu	N r eel Pie ame & embra one um Sli	Alley None e of inspection materials ers & Glass ne ding	INTERIO Floors Walls Trim/Finis Bath Floo	R mate Wood, Tile Drywall sh Wood or Tile inscot Tile	erials
	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centu Year Built 1956 Effective Age (Yrs) 1	ESCRIPTION //Acc. unit S-Det./End sedUnder C .rry Modern	X C Fi Unit Baser Const. Baser	FOUNT FOUNT oncrete Slab [ ull Basement [ nent Area nent Finish utside Entry/Exit	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type	CRIPTION s Sta Fra Me spouts Nc Alu	N r eel Pie ame & embra one um Sli pact C	Alley None e of inspection materials ers & Glass ne ding Glass	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive	IR mate Wood, Tile Drywall sh Wood or Tile inscot Tile age X None eway # of Cars	erials
	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern	X C FI Unit Baser Const. Baser O Heatin	FOUNI FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities	CRIPTION s Ste Fra Me spouts No Alu lated Im Ye	N r eel Pie ame & embrai one um Slii ipact G ss Wor	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive Driveway	R mate Wood, Tile brywall sh Wood or Tile inscot Tile age X None way # of Cars y Surface Pavers	erials e
ITS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic	ESCRIPTION //Acc. unit S-Det./End sedUnder C ury Modern  X None Stairs	Const. Baser	FOUNI FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ng [X] FWA [	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s)	CRIPTION s Ste Fra Me spouts No Alu lated Im Ye	N r eel Pie ame & embra one um Sliu pact G ss  Woo	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive Driveway	R mate Wood,Tile Drywall sh Wood or Tile inscot Tile age X None eway # of Cars ge # of Cars	erials e
MENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centu Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished	ESCRIPTION //Acc. unit S-Det./End sedUnder C ury Modern X None Stairs Scuttle Heated	Const. Baser Const. Const. Cons	FOUNI oncrete Slab [ ull Basement [ nent Area nent Finish utside Entry/Exit ng [X] FWA [ ther ] ng [X] Central dividual _ [	DATION DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None	CRIPTION s Ste Fra Me spouts Noc Alu lated Im Ye ( # 0 (	N r eel Pie ame & embra one um Sli pact G s S Voi Fen Por Oth	Alley None e of inspection materials ers a Glass ne ding Glass odStove(s) #0 nce None cch None er None	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive Driveway	R mate Wood,Tile Drywall sh Wood or Tile inscot Tile age X None eway # of Cars ge # of Cars	erials e
OVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished Appliances X Refriger	ESCRIPTION //Acc. unit	X C FI Unit Baser Const. Baser O Heatin Heatin Coolir Coolir In (Oven X D	FOUNI oncrete Slab [ ull Basement [ nent Area nent Finish utside Entry/Exit ng [X] FWA [ ther ] ng [X] Central a dividual [ ishwasher X]	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microv	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash	CRIPTION s Stu Fra spouts Noc Alu lated Im Ye ( # 0 ( ( er/Dryer	N r eel Pic ame & embrai one um Slii pact G ss  Por Oth Oth	Alley None e of inspection materials ers a Glass ne ding Glass odStove(s) #0 nce None rch None ier None ther (describe)	INTERIO Floors Walls Trim/Finits Bath Floo Bath Wai Car Stora X Drive Driveway Gara Carp Att.	R mate Wood, Tile Drywall sh Wood or Tile inscot Tile age X None eway # of Cars / Surface Pavers ige # of Cars ort # of Cars Det.	erials e 2 Built-in
MPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished Appliances X Refriger Finished area above grade	ESCRIPTION //Acc. unit //Acc.	X C FI Unit Baser Const. Baser O Heatin Heatin Coolir Coolir In (Oven X D	FOUNI oncrete Slab [ ull Basement [ nent Area nent Finish utside Entry/Exit ther ng [X] FWA [ ther dividual [ ishwasher X] i Rooms	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microv 2 Bedrooms	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash	CRIPTION s Ste Fra spouts Noc Alu lated Im Ye ( # 0 ( ( # 0 ( ( er/Dryer .0 Bath(s	N r eel Pie ame & embrai one um Slii pact G ss  Por Oth Oth Oth	Alley None e of inspection materials ers a Glass ne ding Glass odStove(s) #0 nce None rch None ier None ther (describe) 1,430 Squar	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive Driveway Gara Carp Att.	R       mate         Wood, Tile         Drywall         sh       Wood         or       Tile         inscot       Tile         age       X) None         eway       # of Cars         / Surface       Pavers         inge       # of Cars         / Surface       Pavers         inge       # of Cars         Other       Det.	erials e 2 Built-in Nbove Grade
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished Appliances X Refriger	ESCRIPTION //Acc. unit //Acc. Under C ised //Acc. Under C ury Modern //Acc. //Acc	X C Fi Unit Baser Const. Baser O Heatin O Coolir O Coolir O Coolir D Seed as if it ha	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng X FWA [ ther ] ng X Central dividual [ ishwasher X i Rooms as been completion	DATION Description	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco	CRIPTION s Ste Fra Me spouts Noc Alu lated Im Ye ( # 0 ( er/Dryer .0 Bath(s pe of wo	N r eel Pie ame & embrai one um Sliu pact C s S Por Por Oth Oth	Alley None e of inspection materials ers a Glass ne ding Glass odStove(s) #0 nce None rch None ther (describe) 1,430 Squar vided by the cl	INTERIO Floors Walls Trim/Finis Bath Floo Bath Wai Car Stora X Drive Driveway Gara Carp Att. re Feet of C ient, tota	R       mate         Wood, Tile         Drywall         sh       Wood         or       Tile         inscot       Tile         age       X None         way       # of Cars         y Surface       Pavers         inge       # of Cars         ort       # of Cars         Det.       Gross Living Area /         Ling +/-\$1,106,3	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished Appliances X Refriger Finished area above grade Additional Features The I Finishes of the home w the historic structure.	ESCRIPTION //Acc. unit //Acc.	X C Fil Unit Baser Const. Baser O Heatin Heatin O Coolir In /Oven X D 5 Seed as if it had d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther itker dividual [ ishwasher X] i Rooms as been completors throughout,	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microv 2 Bedrooms etely reconstructed impact glass wind	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Vindow Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic C Drop Stair C Floor C Finished Age above grade Additional Features The I Finishes of the home w the historic structure. Comments on the Improven	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng [X] FWA [ ther ] ishwasher X] ishwasher X] is Rooms as been completors throughout, nised as though	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Streens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic Drop Stair Floor Finished Appliances X Refriger Finished area above grade Additional Features The I Finishes of the home w the historic structure.	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng [X] FWA [ ther ] ishwasher X] ishwasher X] is Rooms as been completors throughout, nised as though	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Streens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic C Drop Stair C Floor C Finished Age above grade Additional Features The I Finishes of the home w the historic structure. Comments on the Improven	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng [X] FWA [ ther ] ishwasher X] ishwasher X] is Rooms as been completors throughout, nised as though	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Streens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic C Drop Stair C Floor C Finished Age above grade Additional Features The I Finishes of the home w the historic structure. Comments on the Improven	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng [X] FWA [ ther ] ishwasher X] ishwasher X] is Rooms as been completors throughout, nised as though	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Streens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic C Drop Stair C Floor C Finished Age above grade Additional Features The I Finishes of the home w the historic structure. Comments on the Improven	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ther ] ng [X] FWA [ ther ] ng [X] Central a dividual [ ishwasher X] is Rooms as been complet ors throughout,	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Storm Sash/Insu Streens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None er None ther (describe) 1,430 Squar vided by the cl lernize the horr	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora X Drive Driveway Gara Carp Carp Att. re Feet of C ient, tota re, while	IX         IX	erials e 2 Built-in Above Grade 40.
IMPROVEMENTS	GENERAL DE Units X One One w # of Stories 2 Type X Det. Att. X Existing Propos Design (Style) Mid Centur Year Built 1956 Effective Age (Yrs) 1 Attic C Drop Stair C Floor C Finished Age above grade Additional Features The I Finishes of the home w the historic structure. Comments on the Improven	ESCRIPTION //Acc. unit // S-Det./End sed Under C ury Modern X None Stairs Scuttle Heated ator X Range e contains: home is apprais vill include wood ments The sub	X C Const. Baser Const. Baser O Heatin O Coolir I Unit Baser O Coolir I Unit Seed as if it has d and tile floo	FOUNI oncrete Slab [ ull Basement [ ment Area ment Finish utside Entry/Exit ng X FWA [ ther ] ng X Central / dividual [ ishwasher X] is Rooms as been comple ors throughout, nised as though	DATION Crawl Space Partial Basement N/A sq. ft. N/A % Sump Pump HW Radiant Fuel Electric Air Conditioning Other Disposal X Microw 2 Bedrooms etely reconstructed impact glass wind a complete reconstruct	EXTERIOR DES Foundation Wall Exterior Walls Roof Surface Gutters & Downs Window Type Storm Sash/Insu Screens Amenities Fireplace(s) X Patio/Deck Pool None vave X Wash 2 as per the sco ows and doors struction of hist preciation.	CRIPTION s Ste Fra Me spouts Nc spouts Nc Alu lated Im Ye ( uer/Dryer .0 Bath(s pe of wo , etc. tha	N r eel Pie ame & embra one um Sliv pact C s pact C s pact C s pact C s por Por Oth Oth Oth Oth Oth Oth	Alley None e of inspection materials ers & Glass ne ding Glass odStove(s) #0 nce None ch None ther (describe) 1,430 Squai vvided by the cl ernize the home har	INTERIO Floors Walls Trim/Finis Bath Floc Bath Wai Car Stora (X) Drive Driveway Gara (Carp Att. Tre Feet of C ient, tota ne, while	IX         IX	erials erials e 2 2 bove Grade 40. tprint of

appraisalreport

## Residential Appraisal Report

File No. 21-1980 Renovated

		itesiuei				File No. 21-1980 1	(enovaled
FEATURE	SUBJECT	COMPARABLE S	SALE NO. 1	COMPARABLE S	ALE NO. 2	COMPARABLE S	ALE NO. 3
212 Seabreeze Avenue	9	1101 N Vista Del Mai	r Drive	1118 S Vista Del Mar	<sup>-</sup> Drive	218 Andrews Avenue	
Address Delray Beach		Delray Beach		Delray Beach		Delray Beach	
Proximity to Subject		0.08 miles NW		0.04 miles NE		0.07 miles SE	
Sale Price	\$	\$	1,950,000	\$	1,725,000	\$	1,650,000
Sale Price/Gross Liv. Area	\$ 0.00 sq. ft.	\$ 804.79 sq. ft.		\$ 981.23 sq. ft.		\$ 1,195.65 sq. ft.	
Data Source(s)		Beaches #RX-10693	952	Beaches #RX-10644	301	Beaches #RX-10694	775
Verification Source(s)		ORB 32478 P 1610		ORB 32249 P 17558		ORB 32420 P 663	
VALUE ADJUSTMENTS	DESCRIPTION	DESCRIPTION	+(-) \$ Adjustment	DESCRIPTION	+(-) \$ Adjustment	DESCRIPTION	+(-) \$ Adjustment
Sale or Financing		Cash		Cash		Cash	.() •
Concessions		Cush		Cush		Ousir	
		05/01:000/01	1070.000	002/01:001/01	1076 000	001/01:000/01	1221 000
Date of Sale/Time	0	s05/21;c02/21	+273,000	s03/21;c01/21	+276,000	s04/21;c02/21	+231,000
Location	Good	Good		Good		Good	
Leasehold/Fee Simple	Fee Simple	Fee Simple		Fee Simple		Fee Simple	
Site	11419 sf	7162 sf	+238,400	7710 sf	,	6814 sf	+257,900
View	Residential 2 streets	Residential	+20,000	Residential	+20,000	Residential	+20,000
Design (Style)	Mid Century Modern	Traditional		Ranch		Ranch	
Quality of Construction	Good	Good		Good		Good	
Actual Age	1956	1955		1952		1940	
Condition	Good	Good		Good		Good	
Above Grade	Total Bdrms. Baths	Total Bdrms. Baths		Total Bdrms. Baths		Total Bdrms. Baths	
Room Count	5 2 2.0	6 3 3.0	-10,000	6 3 3.1	-15,000	6 3 2.0	0
Gross Living Area 338.00	<b>1,430</b> sq. ft.	<b>2,423</b> sq. ft.	-335,600	<b>1,758</b> sq. ft.	-110,900	<b>1,380</b> sq. ft.	+16,900
			-333,000		-110,300		+10,300
Basement & Finished	None	None		None		None	
Rooms Below Grade							
Functional Utility	Good	Good		Good		Good	
Heating/Cooling	Central	Central		Central		Central	
Energy Efficient Items	None	None		None		None	
Garage/Carport	None	1 Car Garage	-10,000	1 Car Garage	-10,000	1 Car Garage	-10,000
Porch/Patio/Deck	Patio/Deck	Patio/Deck		Patio/Deck		Patio/Deck	
Pool, Spa, etc.	None	None		None		Pool	-50,000
							,
Not Adjustment (Total)		X+ - \$	175,800	X + - \$	367,800	X+ - \$	465,800
Net Adjustment (Total)			175,600		307,000		403,800
Adjusted Sale Price		Net Adj. 9.0%		Net Adj. 21.3%		Net Adj. 28.2%	
of Comparables		Gross Adj. 45.5% \$	2,125,800		2,092,800		2,115,800
Summary of Sales Compari	ison Approach The sale	es used are all older ho	mes on interior r	esidential sites that hav	ve been complete	ely renovated in recent	years. All are
adjusted upward for tim	ne to reflect the increas	ing prices in the subje	ct market. This a	adjustment is made at	2%/month after of	consideration of MLS d	ata for Delray
Beach and data from the	ne FHFA HPI Calculato	or for the local MSA. N	lone are on a site	e the size of the subjec	t site and all requ	uire site size adjustmer	nts, based on
regression analysis of s	site sales on the barrie	island over the past fi	ve years. As the	subject has street fror	ntage along both	Seabreeze Avenue an	d S Vista Del
Mar Drive, the sales are	e all adiusted upward \$	20.000 for the superio	r view based on t	the site sales in the ma	arket. Sales are a	also adiusted for living	area and bath
count and are based or							
				iour a galago ana ina			ouoni -
In reconciling the sales	emphasis is given to	the lower end of the va	lue range as the	subject has only two	hedrooms		
			inde range, as the		beurooms.		
r							
			-				
Discussion of methods and	techniques employed inclu	ding reason for excluding a	an approach to value	The sales compar	ison annroach is	the best indicator of va	alue for the
subject property. The c							
		usveloped as part of th	ແລ ລວອາຊາເມເຍຍາແ.	me moorne approach	is not applicable,	นอ กษากะอ เก แก่ร เกลก	typically
not purchased for inves							
Reconciliation comments:	Direct sales compariso	n analvsis best reflects	s the attitudes of	the typical buyer in the	subiect market	and is given greatest e	mphasis. The
cost approach is not ap							
occupied.							
		141					
Based on the scope of		-					ty that is
the subject of this repo			, which i	s the effective date of			
X Single point \$ 2,1	<u>100,000</u> 🗌 R	ange \$	to \$	Grea		ess than \$	
This appraisal is made	] "as is," 🔄 subject to	completion per plans and s	pecifications on the	basis of a hypothetical con	dition that the improv	vements have been comple	ted,
X subject to the following						subject to the followin	
See attached limiting c							
home that is on the site							
		Produced	using ACI software, 800.234.8	727 www.aciweb.com	This form Convrid	ht © 2005-2016 ACI, a First American C	ompany, All Rights Reserved
nar		Troduceut	Page 2 of 4		ionn oopyngi	(gPAR™) General Purpose GP	Appraisal Report 1/2014
						GP	

eappraisalreport

#### Scope of Work, Assumptions and Limiting Conditions

Scope of work is defined in the Uniform Standards of Professional Appraisal Practice as " the type and extent of research and analyses in an assignment." In short, scope of work is simply what the appraiser did and did not do during the course of the assignment. It includes, but is not limited to: the extent to which the property is identified and inspected, the type and extent of data researched, the type and extent of analyses applied to arrive at opinions or conclusions.

The scope of this appraisal and ensuing discussion in this report are specific to the needs of the client, other identified intended users and to the intended use of the report. This report was prepared for the sole and exclusive use of the client and other identified intended users for the identified intended use and its use by any other parties is prohibited. The appraiser is not responsible for unauthorized use of the report.

The appraiser's certification appearing in this appraisal report is subject to the following conditions and to such other specific conditions as are set forth by the appraiser in the report. All extraordinary assumptions and hypothetical conditions are stated in the report and might have affected the assignment results.

1. The appraiser assumes no responsibility for matters of a legal nature affecting the property appraised or title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable. The property is appraised as though under responsible ownership.

2. Any sketch in this report may show approximate dimensions and is included only to assist the reader in visualizing the property. The appraiser has made no survey of the property.

3. The appraiser is not required to give testimony or appear in court because of having made the appraisal with reference to the property in question, unless arrangements have been previously made thereto.

4. Neither all, nor any part of the content of this report, copy or other media thereof (including conclusions as to the property value, the identity of the appraiser, professional designations, or the firm with which the appraiser is connected), shall be used for any purposes by anyone but the client and other intended users as identified in this report, nor shall it be conveyed by anyone to the public through advertising, public relations, news, sales, or other media, without the written consent of the appraiser.

5. The appraiser will not disclose the contents of this appraisal report unless required by applicable law or as specified in the Uniform Standards of Professional Appraisal Practice.

6. Information, estimates, and opinions furnished to the appraiser, and contained in the report, were obtained from sources considered reliable and believed to be true and correct. However, no responsibility for accuracy of such items furnished to the appraiser is assumed by the appraiser.

7. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render it more or less valuable. The appraiser assumes no responsibility for such conditions, or for engineering or testing, which might be required to discover such factors. This appraisal is not an environmental assessment of the property and should not be considered as such.

8. The appraiser specializes in the valuation of real property and is not a home inspector, building contractor, structural engineer, or similar "expert", unless otherwise noted. The appraiser did not conduct the intensive type of field observations of the kind intended to seek and discover property defects. The viewing of the property and any improvements is for purposes of developing an opinion of the defined value of the property, given the intended use of this assignment. Statements regarding condition are based on surface observations only. The appraiser claims no special expertise regarding issues including, but not limited to: foundation settlement, basement moisture problems, wood destroying (or other) insects, pest infestation, radon gas, lead based paint, mold or environmental issues. Unless otherwise indicated, mechanical systems were not activated or tested.

This appraisal report should not be used to disclose the condition of the property as it relates to the presence/absence of defects. The client is invited and encouraged to employ qualified experts to inspect and address areas of concern. If negative conditions are discovered, the opinion of value may be affected.

Unless otherwise noted, the appraiser assumes the components that constitute the subject property improvement(s) are fundamentally sound and in working order.

Any viewing of the property by the appraiser was limited to readily observable areas. Unless otherwise noted, attics and crawl space areas were not accessed. The appraiser did not move furniture, floor coverings or other items that may restrict the viewing of the property.

9. Appraisals involving hypothetical conditions related to completion of new construction, repairs or alteration are based on the assumption that such completion, alteration or repairs will be competently performed.

10. Unless the intended use of this appraisal specifically includes issues of property insurance coverage, this appraisal should not be used for such purposes. Reproduction or Replacement cost figures used in the cost approach are for valuation purposes only, given the intended use of the assignment. The Definition of Value used in this assignment is unlikely to be consistent with the definition of Insurable Value for property insurance coverage/use.

11. The ACI General Purpose Appraisal Report (GPAR<sup>™</sup>) is not intended for use in transactions that require a Fannie Mae 1004/Freddie Mac 70 form, also known as the Uniform Residential Appraisal Report (URAR).

#### Additional Comments Related To Scope Of Work, Assumptions and Limiting Conditions

Scope of Work: As part of this assignment, the appraiser has: 1. performed a complete visual inspection of the interior and exterior areas of the subject property, 2. inspected the subject neighborhood, 3. inspected each of the comparable sales from at least the street, 4. researched, verified, and analyzed the data from reliable public and/or private sources, 5. reported the analysis, conclusions, and opinions in this appraisal report.

Extraordinary Assumption: It is assumed that the prior improvements to the site, considered a historic structure by the City of Delray Beach, have been reconstructed in a manner consistent with the reconstruction of older homes and with the work all done in accordance with local building codes.

## **Residential Appraisal Report**

#### Appraiser's Certification

The appraiser(s) certifies that, to the best of the appraiser's knowledge and belief:

1. The statements of fact contained in this report are true and correct.

2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are the appraiser's personal, impartial, and unbiased professional analyses, opinions, and conclusions.

3. Unless otherwise stated, the appraiser has no present or prospective interest in the property that is the subject of this report and has no personal interest with respect to the parties involved.

- 4. The appraiser has no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 5. The appraiser's engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 6. The appraiser's compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 7. The appraiser's analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 8. Unless otherwise noted, the appraiser has made a personal inspection of the property that is the subject of this report.
- 9. Unless noted below, no one provided significant real property appraisal assistance to the appraiser signing this certification. Significant real property appraisal assistance provided by:

#### Additional Certifications:

The reported analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Code of Professional Ethics and Standards of Professional Appraisal Practice of the Appraisal Institute.

The use of this report is subject to the requirements of the Appraisal Institute relating to review by its duly authorized representatives.

The reported analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the requirements of the State of Florida relating to review by the Florida Real Estate Appraisal Board.

As of the date of this report, I have completed the continuing education program for Designated Members of the Appraisal Institute.

Definition of Value: X Market Value Other Value:

Source of Definition: Chapter 12, Code of Federal Regulation; Part 34.42 (f)

The most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

buyer and seller are typically motivated;

both parties are well informed or well advised, and acting in what they consider their best interest;

a reasonable time is allowed for exposure in the open market;

payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and

the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

ADDRESS OF THE PROPERTY APPRAISED:	
212 Seabreeze Avenue	
Delray Beach, FL 33483	
EFFECTIVE DATE OF THE APPRAISAL: 10/01/2021	
APPRAISED VALUE OF THE SUBJECT PROPERTY \$ 2,100,000	
APPRAISER	SUPERVISORY APPRAISER
Signature:	Signature:
Name: David Aucamp, SRA	Name:
Company Name: Aucamp, Dellenback & Whitney	Company Name:
Company Address: 1900 NW Corporate Blvd 215E	Company Address:
Boca Raton, Florida 33431	
Telephone Number: 561-609-2890	Telephone Number:
Email Address: david@adw-appraisers.com	Email Address:
State Certification # Cert Res RD366	State Certification #
or License #	or License #
or Other (describe): State #:	State:
State: FL	Expiration Date of Certification or License:
Expiration Date of Certification or License: 11/30/2022	Date of Signature:
Date of Signature and Report: 10/18/2021	Date of Property Viewing:
Date of Property Viewing: 10/01/2021	Degree of property viewing:
Degree of property viewing:         Interior and Exterior         X         Exterior Only         Did not personally view	Interior and Exterior Exterior Only Did not personally view
Produced using ACI software, 800	234.8727 www.aciweb.com This form Copyright © 2005-2016 ACI, a First American Company. All Rights Reserve

#### ADDENDUM

Client: Michael Marco	File No.: 21-1980 Renovated		
Property Address: 212 Seabreeze Avenue	Case No.:		
City: Delray Beach	State: FL	Zip: 33483	

#### **Neighborhood Boundaries**

The subject lies north of Linton Blvd, south of George Bush Blvd, east of the Intracoastal Waterway and west of Ocean Blvd.

#### Neighborhood Description

The subject is located on the barrier island in close proximity to the downtown area of Delray Beach. The proximity to the ocean and Atlantic Avenue's shops and restaurants make it appealing. Homes along the Intracoastal Waterway are indicative of the upper end of the subject market. Homes on interior sites are the least expensive, but still command a premium because of the location.

As demand for this area has grown, many older homes have been razed and replaced with new contemporary homes. This is the trend throughout South Florida and is prevalent in the waterfront areas.

Local shopping and services are all located within convenient walking distance.

#### **Highest and Best Use**

The highest and best use of the property as improved is as single family residential. The existing structure is in good repair and is well maintained. It serves the function of single family residential occupancy very well. The site and surrounding neighborhood are zoned for single family residential use only. Therefore, any other use would not be legally permissible. Equally important is the fact that the structure was designed for single family use and this time no other use would be physically or financially feasible.

Apprais	er:	-1	Ø	H	
Name:		d Auca	amp, i	SRA	

Supervisory Appraiser:

Addendum Page 1 of 1

Name:

## **USPAP ADDENDUM**

Borrower				
Property City:	Address: 212 Seabreeze Avenue Delray Beach	County: Palm Beach	State: FL	Zip Code: 33483
Lender:	Michael Marco			
APPRA	ISAL AND REPORT IDEN	TIFICATION		
This rep	port was prepared under th	e following USPAP reporting	option:	
X Ap	opraisal Report	A written report prepared under Stan	dards Rule 2-2(a).	
🗌 Re	estricted Appraisal Report	A written report prepared under Stan	dards Rule 2-2(b).	
Reaso	nable Exposure Time			
My opinio	on of a reasonable exposure time f	for the subject property at the market v	value stated in this report is: <u>1-3 m</u>	onths
	time is the estimated length of time ation of a sale at market value on t	e that the property interest being apprai he effective date of the appraisal.	ised would have been offered on th	e market prior to the hypothetical
Additi	onal Certifications			
	ve performed <b>NO</b> services, as an od immediately preceding accepta	appraiser or in any other capacity, reg nce of this assignment.	arding the property that is the subj	ect of this report within the three-year
		praiser or in another capacity, regardin nce of this assignment. Those service:		
Additic	onal Comments			
APPR/	AISER:		SUPERVISORY APPRAISER (c	only if required):
Signatu	ıre:		Signature:	
Name:	David Aupamp, SRA		Name:	
	igned: <u>10/18/2021</u> Certification #: <u>Cert Res RD366</u>			
or State	e License #:		or State License #:	
State:	FL	State #:	State: Expiration Date of Certification of	r License:
Expirat	ion Date of Certification or License	<u>: 11/30/2022</u>	Supervisory Appraiser inspection	n of Subject Prop <u>ert</u> y:
Effectiv	ve Date of Appraisal: October 1, 20	<u></u>	Did Not     Exterior-on	ly from street 🔲 Interior and Exterior
		Produced using ACI software, 80	00.234.8727 www.aciweb.com	USPAP_140427201

## SUBJECT PROPERTY PHOTO ADDENDUM

Client: Michael Marco	File No.: 21-1980 Renovated
Property Address: 212 Seabreeze Avenue	Case No.:
City: Delray Beach	State: FL Zip: 33483



## FRONT VIEW OF SUBJECT PROPERTY

Appraised Date: October 1, 2021 Appraised Value: \$ 2,100,000







## STREET SCENE

## COMPARABLE PROPERTY PHOTO ADDENDUM

Client: Michael Marco	File No.: 21-1980 Renovated
Property Address: 212 Seabreeze Avenue	Case No.:
City: Delray Beach	State: FL Zip: 33483



## COMPARABLE SALE #1

1101 N Vista Del Mar Drive Delray Beach Sale Date: s05/21;c02/21 Sale Price: \$ 1,950,000




## COMPARABLE SALE #2

1118 S Vista Del Mar Drive Delray Beach Sale Date: s03/21;c01/21 Sale Price: \$ 1,725,000



## COMPARABLE SALE #3

218 Andrews Avenue Delray Beach Sale Date: s04/21;c02/21 Sale Price: \$ 1,650,000




 PLAT MAP

 Client:
 Michael Marco
 File No.:
 21-1980 Renovated

 Property Address:
 212 Seabreeze Avenue
 Case No.:


 City:
 Delray Beach
 State:
 FL
 Zip:
 33483

# DELRAY BEACH ESPLANADE



## **AERIAL MAP**

Client: Michael Marco	File	No.: 21-1980 Renovated
Property Address: 212 Seabreeze Avenue	Cas	e No.:
City: Delray Beach	State: FL	Zip: 33483



1900 NW Corporate Blvd Suite 215E, Boca Raton, Florida 33431

### LOCATION MAP

Client: Michael Marco	File N	0.: 21-1980 Renovated
Property Address: 212 Seabreeze Avenue	Case	No.:
City: Delray Beach	State: FL	Zip: 33483



1900 NW Corporate Blvd Suite 215E, Boca Raton, Florida 33431

Client: Michael Marco	File	No.: 21-1980 Renovated	
Property Address: 212 Seabreeze Avenue	Case	e No.:	
City: Delray Beach	State: FL	Zip: 33483	

