



broken fence door



broken gate



broken sliding gate



fence facing north



fence looking east

A photograph of a residential property. In the foreground, a mailbox with a silver and green design and the number '244' is mounted on a grey post. The mailbox is situated on a decorative bed of dark grey and white pebbles. Behind the mailbox, there is a lush green lawn and various tropical plants, including palm trees and a large green plant with broad leaves. In the background, a white fence is visible, and behind it, a blue house with a white roof can be seen. The sky is blue with some clouds.

fence not visible from 7th Ave



Franklin residence compliments white fence



middle fence



neighbor PVC fence historic



neighboring PVC alley



neighboring fence historic



neighboring PVC fence in historic district



rotting bottom fence



rot on bottom fence



view fence from neighbor